







BLOCK @ MIDSPAN




MECH. DUCT OPENING IN HEADER




ROOFING @ MODLINE




HEADER REINF. @ A.C. OPENING




ROOF PAN (26GA.)




MODULE JOINT @ FLR.



ROOFING @ MODLINE



FLOOR FRAME/JOIST TO BEAM



ELEVATION-OPENING

NOTES

- 1 CAP CLOSURE @ RIDGE 26GA. GALV. W/ #10 TYPE FASTENERS W/ NEOPRENE WASHERS TO RIB BOTH SIDES OF MODLINE. SET CAP IN SEALANT SEE DETAIL-
- 2 5/8" M.B. A307 MODULE JOINT (SEE STRUCTURAL PLAN FOR LOCATION)
- 3 E.N.
- 4 MODULE JOINT
- 5 1/4" FULL DEPTH STIFFENER PLATE (SEE STRUCTURAL 7/83.1)
- 6 STANDING ROOF SEAM SEE A.2.0 FOR GAGE
- 7 ROOF BEAM (SEE STRUCTURAL 6/83.1 7/83.1)
- 8 PLYWOOD FLOOR SHEATHING
- 9 FLOOR JOIST 6/83.1
- 10 FLOOR BEAM (SEE STRUCTURAL 5/83.1)
- 11 HAND HOLE @ BOLT LOCATION
- 12 PLYWOOD ROOF SHEATHING
- 13
- 14 ROOF HEADER (SEE STRUCTURAL 2/83.1)
- 15 1/4" STIFFENER PLATE 7/83.1 FOR TYP. WELD
- 16 "C" BLOCKING 2/83.1
- 17
- 18
- 19
- 20
- 21 3 1/4" X 1" X 45 1/2" L X 10GA. CHANNEL TOP & BOTTOM CENTER OF OPENING
- 22 ROOF PUR IN 2/83.1

IDENTIFICATION STAMP
DIV. OF THE STATE ARCHITECT
APP03 110318
AC ☒ FLS ☒ SS ☒ EY
DATE 051215

63288
5-4-95

ARCHITECT

ELECTRICAL

STRUCTURAL

MECHANICAL

FIRE MARSHAL

ACCESS COMPLIANCE

STRUCTURAL SAFETY

JOB # 2058

© MODTECH INC. 1992

DRAWN BY

DATE



CHECKED BY

DATE 5/4/95

STKP-18
4012-064
CLLS.018

STRUCTURAL DETAILS

540



REVISION
4/11/95
2/1/95
IDENTIFICATION STAMP
Department of General Services
Office of the State Architect
May 2 1993
Structural Safety Section
Checked By DE 243 JH/so

