


FIRE ALARM RISER DIAGRAM

FIRE ALARM RISER NOTES

- EXISTING MAIN FIRE ALARM PANEL INSTALLED UNDER DECA #031123K.
- CONTRACTOR SHALL DISCONNECT AND RECONNECT ALL ZONES ASSOCIATED WITH EXISTING BUILDINGS ON CAMPUS AND PROVIDE TESTING FOR POSITIVE REPORTING. PROVIDE FIRE WATCH DURING DEPARTMENT OF SYSTEM PER NFA AND CFC CHAPTER 14+9).

3 *During installation of constructed in Dept Area provide for watch for calls.*



FLEWELLING MOODY
architects for education

HEADQUARTERS OFFICE:
41 South Lee Avenue, Suite 200
Baltimore, MD 21201
Tel: 410.524.1000
Fax: 410.524.1001
Email: flewellingsmoody.com

ANNELOPE VALLEY OFFICE:
1025 West Limestone Boulevard
8510 Woodlawn
Elkton, MD 21921
Tel: 410.326.1000
Fax: 410.326.1001
Email: flewellingsmoody.com

An Outgrowth, Great Collaboration

PROJECT:

CONSULTANT:

CLIENT:

JMPE
11111 RIVERVIEW
ELKTON, MD 21921
TEL: 410.326.1000
FAX: 410.326.1001
WWW.JMPE.COM

PROFESSIONAL SEAL:
JAMES M. PETERSON
REGISTERED PROFESSIONAL ENGINEER
NO. 11111
STATE OF MARYLAND
EXPIRES 12/31/2010

IDENTIFICATION STAMP:
DIV OF THE STATE ARCHITECT
ARCHD 112817
AC
DATE: 02/08/10

**MODERNIZATION PROJECT AT
EMERSON ELEMENTARY SCHOOL**
2800 ROSE LAURE DRIVE
BANGOR, VA 25304

BANGORFIELD CITY SCHOOL DISTRICT

DESIGNED BY: AC

CHECKED BY: PH

DATE: 02/08/10

NO.: 1-14-2009

DATE: 02/08/10

1894200

E-03